

Cheri Sawyer

From: Shyam Sunder [sunder@nist.gov]
Sent: Friday, October 08, 2004 9:22 AM
To: cauffman@nist.gov; cheri.sawyer@nist.gov; john.eichner@nist.gov
Subject: Fwd: WTC - Fireproofing repair

>X-Sieve: CMU Sieve 2.2
>From: "Bhol, Saroj" <sbhol@panynj.gov>
>To: "'hsl@nist.gov'" <hsl@nist.gov>
>Cc: "Begley, James" <jbegley@panynj.gov>, "Fadavi, Ali"
> <afadavi@panynj.gov>,
> "Lin, C. John" <jlin@panynj.gov>, "Lombardi, Frank" <flombard@panynj.gov>,
> "Reiss, Alan"
> <areiss@panynj.gov>,
> "Shyam Sunder (E-mail)" <sunder@nist.gov>
>Subject: WTC - Fireproofing repair
>Date: Fri, 8 Oct 2004 09:20:45 -0400
>X-Mailer: Internet Mail Service (5.5.2657.72)
>X-MailScanner:
>X-MailScanner-From: sbhol@panynj.gov
>
>Dr. Lew,
>
>Here's the response to your question on repair of damaged or missing
>fireproofing in the towers:
>
> According to staff from the former World Trade Department, missing
>or damaged fireproofing that were reported in the Structural
>Integrity Inspection Reports were routinely repaired. The Structural
>Integrity Inspection Reports, which were kept off-site, only are
>available. All construction records were kept at WTC and were destroyed
>on 9/11/01.
>
>Thanks
>Saroj

=====

Dr. S. Shyam Sunder
Acting Deputy Director
Building and Fire Research Laboratory
National Institute of Standards and Technology Gaithersburg, MD 20899-8600
Tel.: 301-975-6850; Fax: 301-975-4032

=====